

Oil Field Environmental Incident Summary

Incident: 20131222204439 **Date/Time of Notice:** 12/22/2013 20:33

Responsible Party: Hess Corporation

Well Operator: HESS CORPORATION

Well Name: AN-EVENSON 152-95-0310H-5

Field Name: ANTELOPE

Well File #: 25698

Date Incident: 12/22/2013 **Time Incident:** 1245

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 95

Sec: 3

Qtr:

Location Description:

Submitted By: Michael Hyndman

Received By:

Contact Person:

3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Miles

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.2	barrels	1.2	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels	1.5	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/21/2014

Clean Up Concluded: 12/22/2013

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The rig crew was able to stop the leak by placing a 2x4 and a bag of fly ash against the crack. A vac truck was called to remove the remaining OBM from the bin and was transferred to a 400 bbl upright. Cleanup of the OBM began immediately using the rigs mud vac system. 100% of the OBM was recovered and returned to the active mud system.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/23/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident report, this spill of oil-based mud occurred at an active drilling rig and was contained on the drilling location. NDIC retains oversight.